



Selling a GM Blower Motor Resistor?

**Remember
The Pigtail!**



PS14

WARNING: High Failure Part!!!


Check for clogged cabin air filter (if equipped)


Check for high amp draw on blower motor

BMR3




BMR31




The  *PS14 is the correct
pigtail for ALL of these BMR's*

BMR14



BMR17



BMR21

